Ministry of Education - Capital Management Branch

2020/21 REPORT FOR TESTING LEAD CONTENT IN DRINKING WATER OF SCHOOL FACILITIES

School District Information		Health Authority (HA) Information	
SD No.	34	Region	Fraser Health
SD Name	Abbotsford	Contact Name	Blair Choquette
SD Contact Name:	Bob Beukers	Contact Phone	1-604-870-7921
SD Contact Phone:	1-604-897-0499	Report Submitted to HA	Yes
Report Date	March 30/ 2022	Report Submission Date	March 30/ 2022

Click here to access the School Master List for Facility Names and Facility Codes

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434506	Abbotsford Arts Center	1981	Nov-19	4	Water Fountain	Room A201	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434506	Abbotsford Arts Center	1981	Nov-19	4	Sink	Kitchen room A210B	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434506	Abbotsford Arts Center	1981	Nov-19	4	Water Fountain	Room G108	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434506	Abbotsford Arts Center	1981	Nov-19	4	Water Fountain	Room G114	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434025	Abbotsford Middle	2007	Dec-20	5	Sink	Room 118	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434025	Abbotsford Middle	2007	Dec-20	5	Sink	Room 122	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434025	Abbotsford Middle	2007	Dec-20	5	Sink	Room 160 (Teaching)	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434025	Abbotsford Middle	2007	Dec-20	5	Sink	Room 232	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434025	Abbotsford Middle	2007	Dec-20	5	Sink	Room 112	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434022	Abbotsford Senior Secondary	2012	Jan-22	2	Sink	Room R102B	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434022	Abbotsford Senior Secondary	2012	Jan-22	8	Sink	Room R100F	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434022	Abbotsford Senior Secondary	2012	Jan-22	8	Sink	Room R105 (Meat/Veg)	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434022	Abbotsford Senior Secondary	2012	Jan-22	8	Sink	Room R108B	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434022	Abbotsford Senior Secondary	2012	Jan-22	8	Sink	Room G100C	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434022	Abbotsford Senior Secondary	2012	Jan-22	2	Sink	Room A213	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434022	Abbotsford Senior Secondary	2012	Jan-22	8	Water Fountain	Room G101	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434022	Abbotsford Senior Secondary	2012	Jan-22	8	Water Fountain	Room G114	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434061	Abbotsford Traditional Senior Secondary	1960	Nov-19	8	Water Fountain	Room C232	0.015	Yes	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	under seismic project	Nov-22	30-Mar-22
34	3434061	Abbotsford Traditional Senior Secondary	1960	Nov-19	8	Water Fountain	Room C244	0.012	Yes	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	under seismic project	Nov-22	30-Mar-22

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434061	Abbotsford Traditional Senior Secondary	1960	Nov-19	8	Water Fountain	Room C255	0.008	Yes	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	under seismic project	Nov-22	30-Mar-22
34	3434061	Abbotsford Traditional Senior Secondary	1960	Nov-19	8	Water Fountain	Room C132	0.013	Yes	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	under seismic project	Nov-22	30-Mar-22
34	3434061	Abbotsford Traditional Senior Secondary	1960	Nov-19	8	Water Fountain	Room C144	0.014	Yes	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	under seismic project	Nov-22	30-Mar-22
34	3434061	Abbotsford Traditional Senior Secondary	1960	Nov-19	8	Water Fountain	Room S112	0.012	Yes	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	under seismic project	Nov-22	30-Mar-22
34	3434061	Abbotsford Traditional Senior Secondary	1960	Nov-19	8	Water Fountain	Hallway 160	0.016	Yes	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	under seismic project	Nov-22	30-Mar-22
34	3434061	Abbotsford Traditional Senior Secondary	1960	Nov-19	8	Sink	Room E169A	0.176	Yes	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	under seismic project	Nov-22	30-Mar-22
34	3499101	Abbotsford Virtual School	1929	Nov-19	4	Water Fountain	Corridor 111	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3499101	Abbotsford Virtual School	1929	Nov-19	4	Sink	Kitchen room 113E	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3499101	Abbotsford Virtual School	1929	Nov-19	4	Water Fountain	Room 203	0.005	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434026	Aberdeen Elementary	1955	Nov-19	5	Water Fountain	R111	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434026	Aberdeen Elementary	1955	Nov-19	5	Water Fountain	R122	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434026	Aberdeen Elementary	1955	Nov-19	5	Water Fountain	R124	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434026	Aberdeen Elementary	1955	Nov-19	5	Sink	R127	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434030	Aboriginal Education Centre	1961	Nov-19	3	Sink	Room 103	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434030	Aboriginal Education Centre	1961	Nov-19	3	Water Fountain	Room 102	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434030	Aboriginal Education Centre	1961	Nov-19	3	Sink	Room 102	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434021	Alexander Elementary	1951	Nov-19	5	Water Fountain	Girls 115	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434005	ASIA North Poplar Elementary	1922	Nov-19	5	Water Fountain	Room 153	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434005	ASIA North Poplar Elementary	1922	Nov-19	5	Water Fountain	Room E113	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434005	ASIA North Poplar Elementary	1922	Nov-19	5	Sink	Room 127	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434005	ASIA North Poplar Elementary	1922	Nov-19	5	Water Fountain	Room E107	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434035	Auguston Traditional Elementary	2000	Dec-20	7	Sink	Room 112	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434035	Auguston Traditional Elementary	2000	Dec-20	7	Sink	Room 219	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434035	Auguston Traditional Elementary	2000	Dec-20	2	Sink	Room 222	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Feb-23	30-Mar-22
34	3434035	Auguston Traditional Elementary	2000	Dec-20	7	Sink	Room 115	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434035	Auguston Traditional Elementary	2000	Dec-20	7	Sink	Room 126	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434035	Auguston Traditional Elementary	2000	Dec-20	7	Sink	Room 210F	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434000	Bakerview Centre for Learning	1973	Nov-19	4	Water Fountain	N133	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434000	Bakerview Centre for Learning	1973	Nov-19	4	Water Fountain	Womens S120	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434000	Bakerview Centre for Learning	1973	Nov-19	4	Sink	Staffroom N230	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434000	Bakerview Centre for Learning	1973	Nov-19	4	Water Fountain	Staffroom N230	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434023	Barrowtown Elementary	1952	Nov-19	4	Sink	R102	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434023	Barrowtown Elementary	1952	Nov-19	4	Water Filling Station	R112	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434023	Barrowtown Elementary	1952	Nov-19	4	Sink	R118	0.005	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434049	Blue Jay Elementary	1989	Nov-19	8	Sink	Kitchen 103C	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434049	Blue Jay Elementary	1989	Nov-19	8	Water Fountain	112C right	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434049	Blue Jay Elementary	1989	Nov-19	8	Water Fountain	112C left	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434049	Blue Jay Elementary	1989	Nov-19	8	Water Fountain	R122	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434049	Blue Jay Elementary	1989	Nov-19	8	Water Fountain	R123	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434011	Bradner Elementary	1925	Nov-19	5	Other	E117	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434011	Bradner Elementary	1925	Nov-19	5	Water Filling Station	S101	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434037	Centennial Park Elementary	1968	Nov-19	6	Water Fountain	Room 119E	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434037	Centennial Park Elementary	1968	Nov-19	6	Water Fountain	Room 114	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434037	Centennial Park Elementary	1968	Nov-19	6	Water Fountain	Room 201	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3499055	Center for Resource Education	unknown	Nov-19	3	Sink	Room 105	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3499055	Center for Resource Education	unknown	Nov-19	3	Sink	Ladies 217	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3499055	Center for Resource Education	unknown	Nov-19	3	Sink	Staff 302	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434047	Chief Dan George Middle	1984	Nov-19	7	Water Fountain	R102	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434047	Chief Dan George Middle	1984	Nov-19	7	Water Fountain	R147	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434047	Chief Dan George Middle	1984	Nov-19	7	Water Fountain	R177	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434047	Chief Dan George Middle	1984	Nov-19	7	Water Fountain	R117	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434047	Chief Dan George Middle	1984	Nov-19	7	Water Fountain	R110F	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434060	Clayburn Middle	2003	Jan-22	8	Sink	Room 109	0.005	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434060	Clayburn Middle	2003	Jan-22	9	Sink	Room 150 (Teacher)	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434060	Clayburn Middle	2003	Jan-22	8	Sink	Room 172	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434060	Clayburn Middle	2003	Jan-22	8	Sink	Room 209	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434060	Clayburn Middle	2003	Jan-22	8	Sink	Room 252	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434060	Clayburn Middle	2003	Jan-22	9	Sink	Room 143	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434060	Clayburn Middle	2003	Jan-22	9	Sink	Room 175	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434060	Clayburn Middle	2003	Jan-22	9	Water Fountain	Room 101A	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434060	Clayburn Middle	2003	Jan-22	9	Water Fountain	Room 177A	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434018	Clearbrook Elementary	1951	Nov-19	7	Water Fountain	R104F	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434018	Clearbrook Elementary	1951	Nov-19	7	Sink	104G	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434018	Clearbrook Elementary	1951	Nov-19	7	Water Fountain	111F	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434018	Clearbrook Elementary	1951	Nov-19	7	Water Fountain	R127A	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434057	Colleen and Gordie Howe Middle	2001	Dec-20	10	Sink	Room 109	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434057	Colleen and Gordie Howe Middle	2001	Dec-20	10	Sink	Room 150 (Teacher)	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434057	Colleen and Gordie Howe Middle	2001	Dec-20	10	Sink	Room 172	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434057	Colleen and Gordie Howe Middle	2001	Dec-20	10	Sink	Room 209	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434057	Colleen and Gordie Howe Middle	2001	Dec-20	10	Sink	Room 252	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434057	Colleen and Gordie Howe Middle	2001	Dec-20	10	Sink	Room 143	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434057	Colleen and Gordie Howe Middle	2001	Dec-20	2	Sink	Room 175	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434057	Colleen and Gordie Howe Middle	2001	Dec-20	10	Water Fountain	Room 142A	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434057	Colleen and Gordie Howe Middle	2001	Dec-20	10	Water Fountain	Room 177A	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434057	Colleen and Gordie Howe Middle	2001	Dec-20	10	Water Fountain	Room 201A	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434056	Dave Kandal Elementary	1997	Feb-21	9	Sink	Room E17	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Feb-24	30-Mar-22
34	3434056	Dave Kandal Elementary	1997	Feb-21	9	Sink	Room E05	0.005	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Feb-24	30-Mar-22
34	3434056	Dave Kandal Elementary	1997	Feb-21	9	Sink	Room C10	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Feb-24	30-Mar-22
34	3434056	Dave Kandal Elementary	1997	Feb-21	8	Sink	Room C11	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Feb-24	30-Mar-22
34	3434056	Dave Kandal Elementary	1997	Feb-21	9	Sink	Room C08	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Feb-24	30-Mar-22
34	3434056	Dave Kandal Elementary	1997	Feb-21	8	Sink	Room C18	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Feb-24	30-Mar-22
34	3434056	Dave Kandal Elementary	1997	Feb-21	9	Water Fountain	Room E10	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Feb-24	30-Mar-22
34	3434056	Dave Kandal Elementary	1997	Feb-21	8	Water Fountain	Room C16	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Feb-24	30-Mar-22
34	3434043	Dormick Park Elementary	1977	Nov-19	3	Water Fountain	R132	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
	3434055	Dr. Roberta Bondar Elementary	1997	Dec-20	10	Sink	Room B112	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
	3434055	Dr. Roberta Bondar Elementary	1997	Dec-20	10	Sink	Room A115	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
	3434055	Dr. Roberta Bondar Elementary	1997	Dec-20	10	Sink	Room A103	0.005	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
	3434055	Dr. Roberta Bondar Elementary	1997	Dec-20	10	Sink	Room 112	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
	3434055	Dr. Roberta Bondar Elementary	1997	Dec-20	10	Sink	Room 106	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
	3434055	Dr. Roberta Bondar Elementary	1997	Dec-20	10	Sink	Room A101	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
	3434055	Dr. Roberta Bondar Elementary	1997	Dec-20	10	Sink	Room 103	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
	3434055	Dr. Roberta Bondar Elementary	1997	Dec-20	10	Water Fountain	Room A101	0.005	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
	3434055	Dr. Roberta Bondar Elementary	1997	Dec-20	4	Water Fountain	Room A108	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434045	Dr Thomas Swift Elementary	1980	Nov-19	6	Water Fountain	Staffroom 100	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434045	Dr Thomas Swift Elementary	1980	Nov-19	6	Water Fountain	Room 122	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434045	Dr Thomas Swift Elementary	1980	Nov-19	6	Water Fountain	Gym 139	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434045	Dr Thomas Swift Elementary	1980	Nov-19	6	Water Fountain	Room 147	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434058	Eugene Reimer Middle	2002	Dec-20	9	Sink	Room 109	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434058	Eugene Reimer Middle	2002	Dec-20	9	Sink	Room 150 (Teacher)	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434058	Eugene Reimer Middle	2002	Dec-20	9	Sink	Room 172	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434058	Eugene Reimer Middle	2002	Dec-20	9	Sink	Room 209	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434058	Eugene Reimer Middle	2002	Dec-20	9	Sink	Room 252	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434058	Eugene Reimer Middle	2002	Dec-20	9	Sink	Room 143	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434058	Eugene Reimer Middle	2002	Dec-20	9	Sink	Room 175	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434058	Eugene Reimer Middle	2002	Dec-20	9	Water Fountain	Room 201A	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434058	Eugene Reimer Middle	2002	Dec-20	9	Water Fountain	Room 177A	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434502	Facilities	1985	Nov-19	4	Sink	Kitchen 110A	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434502	Facilities	1985	Nov-19	4	Sink	Room 214	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434502	Facilities	1985	Nov-19	4	Water Filling Station	Lunchroom 250	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434502	Facilities	1985	Nov-19	4	Sink	Cabinet shop	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434028	Godson Elementary	1958	Nov-19	6	Water Fountain	Room 131A	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434028	Godson Elementary	1958	Nov-19	6	Water Fountain	Gym 146	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434028	Godson Elementary	1958	Nov-19	6	Water Fountain	Boys WR 125B	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434051	Harry Sayers Elementary	1992	Dec-20	10	Sink	Room 150	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434051	Harry Sayers Elementary	1992	Dec-20	10	Sink	Room N160	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434051	Harry Sayers Elementary	1992	Dec-20	10	Sink	Room 117	0.005	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434051	Harry Sayers Elementary	1992	Dec-20	10	Sink	Room 104	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434051	Harry Sayers Elementary	1992	Dec-20	10	Sink	Room 131	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434051	Harry Sayers Elementary	1992	Dec-20	10	Water Fountain	Room 155	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434051	Harry Sayers Elementary	1992	Dec-20	10	Water Fountain	Room 147	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434051	Harry Sayers Elementary	1992	Dec-20	10	Water Fountain	Room N163	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434051	Harry Sayers Elementary	1992	Dec-20	10	Water Fountain	Room 117	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434051	Harry Sayers Elementary	1992	Dec-20	10	Water Fountain	Room 102	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434999	Information Technology Centre	1961	Nov-19	1	Sink	Kitchen room 110	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	34334031	Jackson Elementary	1961	Jan-22	4	Sink	Room 100	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	34334031	Jackson Elementary	1961	Jan-22	4	Sink	Room 105	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	34334031	Jackson Elementary	1961	Jan-22	4	Sink	Room 137	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	34334031	Jackson Elementary	1061	Jan-22	4	Water Fountain	Room 128	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Jan-25	30-Mar-22
34	3434044	John Maclure Community School	1979	Nov-19	5	Water Fountain	R116	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434044	John Maclure Community School	1979	Nov-19	5	Water Fountain	R138	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434044	John Maclure Community School	1979	Nov-19	5	Water Fountain	R213	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434019	King Traditional School	1951	Nov-19	4	Water Fountain	R137	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434019	King Traditional School	1951	Nov-19	4	Sink	R140A	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434019	King Traditional School	1951	Nov-19	4	Water Fountain	R109	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434019	King Traditional School	1951	Nov-19	4	Water Fountain	R124	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434033	Margaret Stenerson Elementary	1964	Nov-19	5	Water Fountain	Room 301	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434033	Margaret Stenerson Elementary	1964	Nov-19	5	Water Fountain	Room 205	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434059	Matsqui Elementary	2004	Nov-19	2	Sink	Kitchen 102	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434059	Matsqui Elementary	2004	Nov-19	2	Water Fountain	Boys 148	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434059	Matsqui Elementary	2004	Nov-19	5	Sink	Room 122	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434059	Matsqui Elementary	2004	Nov-19	5	Sink	Room 144	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434059	Matsqui Elementary	2004	Nov-19	5	Sink	Room 116	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434059	Matsqui Elementary	2004	Nov-19	5	Sink	Room 145	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434059	Matsqui Elementary	2004	Nov-19	5	Water Fountain	Room 147	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434027	McMillan Elementary	1923	Nov-19	6	Water Fountain	Room N101	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434027	McMillan Elementary	1923	Nov-19	6	Water Fountain	Room S134A	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434027	McMillan Elementary	1923	Nov-19	6	Water Fountain	Girls S143	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434027	McMillan Elementary	1923	Nov-19	6	Water Fountain	Room S152	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434027	McMillan Elementary	1923	Nov-19	6	Water Fountain	Girls S163	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Sink	Room 154	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434053	Mountain Elementary	1992	Dec-20	9	Sink	Room 122	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Sink	Room 117	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Sink	Room 108	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Water Fountain	Room 159	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Water Fountain	Room 117	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Sink	Room 146	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Water Fountain	Room 146	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434053	Mountain Elementary	1992	Dec-20	9	Water Fountain	Room 145	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434003	Mt Lehman Elementary	1909	Nov-19	6	Water Fountain	115	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434003	Mt Lehman Elementary	1909	Nov-19	6	Water Filling Station	R113	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434048	Prince Charles Elementary	1984	Nov-19	5	Water Fountain	Room 21	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434048	Prince Charles Elementary	1984	Nov-19	5	Water Fountain	Room 25	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434052	Rick Hansen Sr. Secondary	1993	Dec-20	7	Sink	Room E118 (front counter)	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434052	Rick Hansen Sr. Secondary	1993	Dec-20	4	Sink	Room C109	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434052	Rick Hansen Sr. Secondary	1993	Dec-20	4	Sink	Room C119	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434052	Rick Hansen Sr. Secondary	1993	Dec-20	7	Sink	Room C217 (island)	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434052	Rick Hansen Sr. Secondary	1993	Dec-20	7	Water Fountain	Room C108	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434052	Rick Hansen Sr. Secondary	1993	Dec-20	7	Water Fountain	Room C218	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434052	Rick Hansen Sr. Secondary	1993	Dec-20	7	Water Fountain	Room E113	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434054	Robert Bateman Sr. Secondary	1993	Dec-20	7	Sink	Room W110	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434054	Robert Bateman Sr. Secondary	1993	Dec-20	7	Sink	Room W207	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434054	Robert Bateman Sr. Secondary	1993	Dec-20	7	Water Fountain	Room W117	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434054	Robert Bateman Sr. Secondary	1993	Dec-20	7	Water Fountain	Room W106	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434054	Robert Bateman Sr. Secondary	1993	Dec-20	7	Water Fountain	Room W305	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22
34	3434054	Robert Bateman Sr. Secondary	1993	Dec-20	7	Water Fountain	Room N108	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Dec-23	30-Mar-22

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434032	Ross Elementary	1962	Nov-19	5	Water Filling Station	Room 106	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434032	Ross Elementary	1962	Nov-19	5	Sink	Room 107	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434032	Ross Elementary	1962	Nov-19	5	Water Fountain	Room 114	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434032	Ross Elementary	1962	Nov-19	5	Water Fountain	Room 124	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434032	Ross Elementary	1962	Nov-19	5	Sink	Room 127B	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434050	Sandy Hill Elementary	1990	Nov-19	9	Water Fountain	Gym 101	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434050	Sandy Hill Elementary	1990	Nov-19	9	Water Fountain	Room 103	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434050	Sandy Hill Elementary	1990	Nov-19	9	Water Fountain	Girls 101B	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434050	Sandy Hill Elementary	1990	Nov-19	9	Water Fountain	Room 115	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434050	Sandy Hill Elementary	1990	Nov-19	9	Water Fountain	Room 123	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434050	Sandy Hill Elementary	1990	Nov-19	9	Water Fountain	Room 124	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434050	Sandy Hill Elementary	1990	Nov-19	9	Water Fountain	Room 118	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434050	Sandy Hill Elementary	1990	Nov-19	9	Water Fountain	Room 127	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434050	Sandy Hill Elementary	1990	Nov-19	9	Water Fountain	Room 130	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434504	School Board Office	1982	Nov-19	2	Water Filling Station	Coffee room 220A	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434504	School Board Office	1982	Nov-19	2	Water Filling Station	Kitchen room 101	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434016	South Poplar Traditional School	1933	Nov-19	4	Sink	Staffroom 103	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434016	South Poplar Traditional School	1933	Nov-19	4	Water Filling Station	Boys 306	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434036	Ten Broeck Elementary	1966	Nov-19	8	Water Fountain	Room S13	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434036	Ten Broeck Elementary	1966	Nov-19	8	Water Fountain	Room S24	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434036	Ten Broeck Elementary	1966	Nov-19	8	Water Fountain	Room C19	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434036	Ten Broeck Elementary	1966	Nov-19	8	Water Fountain	Room C25	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434036	Ten Broeck Elementary	1966	Nov-19	8	Water Fountain	Room N28	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434036	Ten Broeck Elementary	1966	Nov-19	8	Water Fountain	Room N30	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434036	Ten Broeck Elementary	1966	Nov-19	8	Water Fountain	Room N25	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434036	Ten Broeck Elementary	1966	Nov-19	8	Water Fountain	Room N24	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434046	Terry Fox Elementary	1982	Nov-19	9	Water Fountain	104B	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434046	Terry Fox Elementary	1982	Nov-19	9	Water Fountain	108B	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434046	Terry Fox Elementary	1982	Nov-19	9	Water Fountain	Room 118	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434046	Terry Fox Elementary	1982	Nov-19	9	Water Fountain	Girls 126A	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434046	Terry Fox Elementary	1982	Nov-19	9	Water Fountain	Girls 143C	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434046	Terry Fox Elementary	1982	Nov-19	9	Water Fountain	Room 155	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434007	Upper Sumas Elementary	1918	Nov-19	6	Water Fountain	Room 113	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434007	Upper Sumas Elementary	1918	Nov-19	6	Sink	Kitchen room 114E	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434007	Upper Sumas Elementary	1918	Nov-19	6	Sink	Staff room 207	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434007	Upper Sumas Elementary	1918	Nov-19	6	Water Fountain	Room 210	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434042	WA Fraser Middle School	1978	Nov-19	7	Water Fountain	Room C140	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434042	WA Fraser Middle School	1978	Nov-19	7	Water Fountain	Room E159	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434042	WA Fraser Middle School	1978	Nov-19	7	Water Fountain	Room W111	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434042	WA Fraser Middle School	1978	Nov-19	7	Water Fountain	Room C202	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Water Fountain	103A south	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Water Fountain	103A north	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Sink	Room 315	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Water Fountain	Room 407	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Water Fountain	Room 102	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Sink	Room 103A	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Water Fountain	Room 117C	0.001	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Sink	Room 114H	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Water Fountain	Room 144	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Water Fountain	Room 217	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22

SCHOOL FACILITY INFORMATION				TEST INFORMATION						MITIGATION STRATEGY & PUBLIC COMMUNICATION PLAN		ADDITIONAL INFORMATION		
School District Number	Ministry Facility Code	School Facility Name	Year Built	Date of Test (mm/yyyy)	Total Samples	Water Fixture Type	Room Location	Lead Level Result (mg/L)	Exceed Maximum Acceptable Concentrations	Mitigation Strategy Description	Describe Public Communication Plan	Comments	Next Scheduled Date of Testing (mm/yyyy)	Ministry Submission Period
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Water Fountain	Room 207	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Water Fountain	Room 200	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434041	WJ Mouat Secondary	1973	Nov-19	13	Water Fountain	Room 206	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434038	Yale Secondary	1971	Nov-19	10	Water Fountain	Staff A125	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434038	Yale Secondary	1971	Nov-19	10	Water Fountain	Ladies B117	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434038	Yale Secondary	1971	Nov-19	10	Water Fountain	A132	0.000	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434038	Yale Secondary	1971	Nov-19	10	Water Fountain	Ladies B221	0.003	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434038	Yale Secondary	1971	Nov-19	10	Water Fountain	Ladies B211	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434038	Yale Secondary	1971	Nov-19	10	Water Fountain	Boys B223	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434038	Yale Secondary	1971	Nov-19	10	Water Fountain	D111	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434038	Yale Secondary	1971	Nov-19	10	Sink	Kitchen C124	0.004	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434038	Yale Secondary	1971	Nov-19	10	Water Fountain	A155	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22
34	3434038	Yale Secondary	1971	Nov-19	10	Water Fountain	A138	0.002	No	replacement of shutoff valves, supply lines, faucets and fountains	Consultation with Fraser Health. Communication through our school district website	average of 2 static samples as per Pinchin	Nov-22	30-Mar-22